

10.01.17.00419 SGM 20
10.01.17.00421 SGM 30+40
10.01.17.00422 SGM 50

Anzugsdrehmoment /
Tightening torque
SGM 20 / 30+40 / 50
1,3 / 3,1 / 3,1 Nm

Schraubensicherung
mittelfest /
Screw locking
medium

The diagram shows a vertical SGM component with a blue base. To its right are two circular views of the top flange: the top one has a green checkmark and the bottom one has a red 'X'. Below the component, a dashed box contains two exploded views of a screw and a lock washer being inserted into the base.

10.01.17.00419 SGM 20
10.01.17.00421 SGM 30+40
10.01.17.00422 SGM 50

Anzugsdrehmoment /
Tightening torque
SGM 20 / 30+40 / 50
1,3 / 3,1 / 3,1 Nm

Schraubensicherung
mittelfest /
Screw locking
medium

The diagram shows a vertical SGM component with a blue base. To its right are two circular views of the top flange: the top one has a green checkmark and the bottom one has a red 'X'. Below the component, a dashed box contains two exploded views of a screw and a lock washer being inserted into the base.

30.30.01.01249
Index 00
Status 01.2017

**Montageanweisung /
Assembly instructions**
SGM ADP-E-TRI

© J. Schmalz GmbH
J. Schmalz GmbH
Förder- u. Handhabungstechnik
Aacher Straße 29, D 72293 Glatten
Tel.: +49(0)7443/2403-0
Fax.: +49(0)7443/2403-259
e-mail: info@schmalz.de

www.schmalz.com

30.30.01.01249
Index 00
Status 01.2017

**Montageanweisung /
Assembly instructions**
SGM ADP-E-TRI

© J. Schmalz GmbH
J. Schmalz GmbH
Förder- u. Handhabungstechnik
Aacher Straße 29, D 72293 Glatten
Tel.: +49(0)7443/2403-0
Fax.: +49(0)7443/2403-259
e-mail: info@schmalz.de

www.schmalz.com

10.01.17.00419 SGM 20
10.01.17.00421 SGM 30+40
10.01.17.00422 SGM 50

Anzugsdrehmoment /
Tightening torque
SGM 20 / 30+40 / 50
1,3 / 3,1 / 3,1 Nm

Schraubensicherung
mittelfest /
Screw locking
medium

The diagram shows a vertical SGM component with a blue base. To its right are two circular views of the top flange: the top one has a green checkmark and the bottom one has a red 'X'. Below the component, a dashed box contains two exploded views of a screw and a lock washer being inserted into the base.

10.01.17.00419 SGM 20
10.01.17.00421 SGM 30+40
10.01.17.00422 SGM 50

Anzugsdrehmoment /
Tightening torque
SGM 20 / 30+40 / 50
1,3 / 3,1 / 3,1 Nm

Schraubensicherung
mittelfest /
Screw locking
medium

The diagram shows a vertical SGM component with a blue base. To its right are two circular views of the top flange: the top one has a green checkmark and the bottom one has a red 'X'. Below the component, a dashed box contains two exploded views of a screw and a lock washer being inserted into the base.

30.30.01.01249
Index 00
Status 01.2017

**Montageanweisung /
Assembly instructions**
SGM ADP-E-TRI

© J. Schmalz GmbH
J. Schmalz GmbH
Förder- u. Handhabungstechnik
Aacher Straße 29, D 72293 Glatten
Tel.: +49(0)7443/2403-0
Fax.: +49(0)7443/2403-259
e-mail: info@schmalz.de

www.schmalz.com

30.30.01.01249
Index 00
Status 01.2017

**Montageanweisung /
Assembly instructions**
SGM ADP-E-TRI

© J. Schmalz GmbH
J. Schmalz GmbH
Förder- u. Handhabungstechnik
Aacher Straße 29, D 72293 Glatten
Tel.: +49(0)7443/2403-0
Fax.: +49(0)7443/2403-259
e-mail: info@schmalz.de

www.schmalz.com